



## Bluelight Software

902 Redwood Drive  
Loveland, Co 80538

(970) 461-8554

(970) 461-8555

NFPA Member

Permit #93989593

[www.bluelightsw.com](http://www.bluelightsw.com)

[www.efinitymobile.com](http://www.efinitymobile.com)

[sales@bluelightsw.com](mailto:sales@bluelightsw.com)

[support@bluelightsw.com](mailto:support@bluelightsw.com)

Versatile Data Collection, Dynamic Forms Building  
Providing software solutions to service industries for decades

## BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

### Customer Address:

Bluelight Software, LLC  
902 Redwood Drive  
Loveland, CO 80538  
Phone: (970) 461-8554  
Fax: (970) 461-8555

### Site Address:

Bluelight Software, LLC  
902 Redwood Drive  
Loveland, CO 80538  
Phone: (970) 461-8554  
Fax: (970) 461-8555

Customer #: 111

Contract #: 64554

Job Status: Archived

Job Name: NFPA25 Backflow Prevention Assembly Inspection Sample Report

Contact: Al Riggs

Site #: 344

Inspection Date: 1/21/2009

\*\*\*\*Indicates question was scheduled, but was not answered.

----Indicates question was not scheduled and was therefore not answered.

Installation: New Permit #: 344552  
Assembly Make: BADGER-POWHATAN Serial #: 83545678895  
Model: PVB (Pressure Vacuum Breaker) Size (in.): 1 1/2  
Location Type: Fire Protection System  
Location on Property: \_\_\_\_\_  
Water Supplier: Big Thompson Test Type #: Annual

**TEST FOR DOUBLE CHECK AND REDUCED PRESSURE ASSEMBLIES**

Direction of Flow: Check #1: 75 psid Check #2: 79 psid Relief Valve: Open

Leak Tightness: Check #1: Tight Check #2: Tight

**TEST FOR PRESSURE VACUUM BREAKER**

Check Valve: 71 psid Leak Tightness: Leak Air Inlet: Closed

**REPAIRS AND COMMENTS**


Pass \_\_\_\_\_ Line Pressure: 76 psid

Repairs: Replaced check valve.

Comments: Everything OK

**THIS TESTER CERTIFIES THIS ASSEMBLY MEETS MINIMUM STATE AND LOCAL SPECIFICATIONS**

Inspector Certification #: 3242 Expires: 9/15/2009  
Gauge Type: Standard 468X Last Gauge Calibration Date: 9/13/2006  
Time of Test: 09:36 AM Inspector Phone Number: 273-473-2323

  
\_\_\_\_\_

1/21/2009

Customer: Jim Beam

  
\_\_\_\_\_

1/21/2009

Inspection Technician: